

CENTRAL INTELLIGENCE AGENCY

REPORT

CD NO.

25X1

DATE DISTR. 27 October 1955

NO. OF PAGES 1

NO. OF ENCLS.
(LISTED BELOW)

25X1

SUPPLEMENT TO
REPORT NO.

THIS IS UNEVALUATED INFORMATION

25X1

25X1

2. Shortly after the bridge began bearing heavy traffic, it was discovered that the piers in the river serving as a foundation for the bridge had sunk thirty centimeters. This construction fault reportedly occurred ~~before~~ the new bridge was built from the water level up on the old piers; the builders had not installed new piers. It was not realized that changing currents and subsequent movement of sand had undermined the old piers. The bridge has been closed to traffic and is again undergoing repairs. The entire construction area is enclosed by a high board fence.

25X1

25X1

25X1

ILLEGIB

Page Denied